

Gallery Upgrades



MUSKEGON MUSEUM OF ART

PROJECT DESCRIPTION

Remove existing fabric wall finish and wainscot. Drywall existing substrate to floor to achieve desired outcome

CHALLENGES

Update gallery finished while the nationally accredited Muskegon Museum of Art remains open

Complete finish upgrades inside a tight timeline in order to accommodate scheduled exhibits.

Complete finish upgrades in as cost effective a manner as possible.

Complete finish upgrades without impacting sensitive HVAC systems.

RESULTS

Gallery finish upgrades have been completed in Cannon, Operhall and Wiener Galleries. A collaborative effort with museum staff and volunteers allowed for a seamless, efficient, and cost-effective transition of the galleries into new modern space allowing curators the ability to shape the space to better fit a specific exhibit. HVAC systems were isolated and shut down during various phases of the work to protect the system's integrity. Lighting use has been reduced as a result as well.

LOCATION

296 W. Webster Ave.
Muskegon, MI 49440

YEAR COMPLETED

Spring 2019

COST

\$75,000.00

DELIVERY

Construction Management at Risk